
Copper Smelting

Howe Henry Marion

Title: Copper Smelting

Author: Howe Henry Marion

This is an exact replica of a book. The book reprint was manually improved by a team of professionals, as opposed to automatic/OCR processes used by some companies. However, the book may still have imperfections such as missing pages, poor pictures, errant marks, etc. that were a part of the original text. We appreciate your understanding of the imperfections which can not be improved, and hope you will enjoy reading this book.



J. C. Branner
DEPARTMENT OF THE INTERIOR

BULLETIN

OF THE

UNITED STATES

GEOLOGICAL SURVEY

No. 26



AMERICAN LIBRARY
WASHINGTON
GOVERNMENT PRINTING OFFICE

1885

57

214491

YR 2001 0807NAT2

J. C. Branner

DEPARTMENT OF THE INTERIOR

BULLETIN

OF THE

UNITED STATES
=

GEOLOGICAL SURVEY

No. 26



WASHINGTON
GOVERNMENT PRINTING OFFICE
1885

214491

YANAL OCHOA

UNITED STATES GEOLOGICAL SURVEY

J. W. POWELL, DIRECTOR

COPPER SMELTING


BY

HENRY M. HOWE



26

WASHINGTON
GOVERNMENT PRINTING OFFICE
1885



CONTENTS.

	Page.
Letter of transmittal.....	9
Introduction.....	11
I.	
Reverberatory method for sulphureted ores.....	15
1. Ore roasting.....	16
Roasting in heaps or piles.....	16
Roasting in stalls.....	18
Kiln roasting.....	18
Furnaces for fine ore.....	19
Hasenclever and Helbig's.....	19
Gerstenhöfer's.....	19
Maletra's.....	19
Spence's.....	20
Revolving cylinders.....	21
The Stetefeldt furnace.....	21
Reverberatory furnaces.....	21
Open reverberatories.....	21
Muffles.....	24
Mechanical reverberatories.....	24
Objects of the roasting.....	25
a. Oxidation of the iron, and incidentally of the sulphur.....	25
b. The expulsion of arsenic and antimony.....	25
Pile and stall roasting.....	26
Roasting in reverberatories.....	26
Comparison of heap and reverberatory roasting.....	28
2. Smelting the roasted ore in reverberatories.....	28
Furnace construction.....	28
Fire box.....	28
Fire bridge.....	29
Binding.....	30
Erection of binding.....	32
The masonry.....	32
The bottom or hearth.....	33
Size and shape of hearth.....	34
Chimneys.....	35
Draft.....	35
Separate chimneys.....	35
Central chimneys.....	36
Shape.....	37
Stability.....	38
Iron vs. brick chimneys.....	38
Linings.....	38
Batter.....	38
Gas furnaces.....	39
Smelting operation.....	44

	Page
Reverberatory methods for sulphureted ores — Continued.	
The matte	47
The slag	47
In general	47
Classification	50
Fusibility, simple silicates	50
Multiple silicates	50
Specific gravity	52
Corrosiveness	52
Liquidity	52
Scorification	52
Chemical reactions	53
In general	53
Arsenic and antimony	54
3. Roasting the first matte (coarse metal)	54
The aim	54
The operation	56
4. Smelting roasted coarse metal for white metal	58
The aim	58
The operation	60
Chemical reactions	61
4 a. Smelting roasted coarse metal for blue metal	62
The furnaces	62
The operation	63
4 b. Roasting-smelting the raw blue metal for regule and bottoms	63
The aim	63
The operation	63
Chemical reactions	64
5. Roasting-smelting the raw white metal and regule for blistered copper	66
The aim	66
The operation	66
Classification of ores and slags	70
Ores	70
Slags	72
II.	
Reverberatory method for oxidized ores and native copper	73
Reducing-smelting with carbon	73
Smelting without carbon	74
Comparison of the two methods	74
III.	
Shaft furnace process for sulphureted ores	74
General plan	74
1. Ore roasting	76
2. Ore smelting	76
In general	76
The deoxidizing effect	80
The average temperature of the ore	80
The proportion of fuel to burden	80
The porosity of the fuel	80
The porosity of the ore	80
The intimacy of mixture	80
The basicity of the mixture	80
The infusibility of the mixture	80

CONTENTS.

7

	Page.
Shaft furnace process for sulphureted ores—Continued.	
The preponderance of iron oxide	80
Height <i>vs.</i> width	81
Sulphides	82
Arsenic and antimony	82
Volume of furnace	83
Raschette furnaces	85
Disposition of crucible	86
Internal crucibles	86
Crucibles, partly internal, partly external	87
External crucibles	87
Water-jacketed <i>vs.</i> brick walls	88
Cast <i>vs.</i> wrought-iron jackets	90
Blast, tuyeres, etc.	91
Hot blast	92
Products	92
Matte	92
Slag	93
Details of working	94
Mechanical charging	94
Changing tuyeres	95
Filter charging	95
Fine ore	95
3. Roasting the first matte	96
4. Smelting the roasted first matte	96
Products	98
Black copper	98
Matte	98
Slags	98

IV.

Shaft furnace process for oxidized ores and native copper	99
---	----

V.

Comparison of the reverberatory and shaft furnace methods	99
Composition of charge	99
Labor and fuel	99
Arsenic and antimony	100
Technical skill	101
The first cost of construction	101
Repairs	101
The loss of copper	101
Fines	101
Salamanders	101
Rapidity	101
Size of establishment	102
Bringing forward	102

VI.

Résumé	102
--------------	-----

ADDENDUM.

Matte roasting in reverberatory furnaces at the Orford Copper and Sulphur Works	103
---	-----